RESTORING THE 1948 MEISSNER 8C "RECEPTOR" FM TUNER*





* Video of restored operation is on the CHRS website.

<< Note Channel Numbers 200 to 300

A presentation by Bart Lee, K6VK for the California Historical Radio Society, © 2017

AND MANY A MISTAKE ALONG THE WAY!

MEISSNER MFG. DIV., MAGUIRE INDUSTRIES, INC.

Sixty three radios and types of parts (1937 to mid-1950s) are listed for the radio manufacturer Meissner Mfg. Div., Maguire Industries, Inc. (Mt. Carmel, IL) by <u>www.RadioMuseum.org</u>. The product line included test equipment and kits. The 1937 radio was a communications receiver for hams and SWLs.

A war-profiteering wheeler-dealer named Maguire, as Maguire Industries, in order to get into the radio business after World War Two, bought and merged Meissner with Thordarson, also newly acquired. (From *Tommy Gun: How General Thompson's Submachine Gun Wrote History*, By Bill Yenne (2009)). Meissner also sold radios, at least as of 1946, under the Brewster trade name.

Whether the Meissner radio company ever had any connection with German radio pioneer Alexander Meissner cannot readily be determined. See <u>http://ethw.org/Alexander_Meissner</u>.

Meissner 8-C Documentation:



This FM Tuner Uses 7 Miniature Tubes



From Most Needed Radio Schematics (1949)

The Cabinet Is Plywood, Veneered With The Two Corners Scored And (Steam) Bent:



Masking Tape (Fossilized) Once Perhaps Held A Back Cover On The Tuner:



A Solvent And A Scraper Got The Tape Off:





Needless to say, the tape had to be soaked for a while and the scraper wielded with considerable delicacy. The WD-40 did no damage to the finish. The cabinet now seems restorable; on to the guts!

A LETHAL SHOCK HAZARD:



Inspect for safety!

Cleaning The Chassis With 90% Alcohol And Cotton Tipped Sticks:



Decades of Dust and Tobacco Tars!

Use a Solvent? Use Hot Water?



Test the Solvent on a Tiny Bit of Paint First!

Photograph The Dial-Stringing – Just In Case!



Examine Under The Chassis For Issues And Catalog The Parts:



Is Overheating An Issue? The Cap Is Surely Bad; Is The Resistor?



Caps Identified:



Inventory All Caps; Identify on Chassis and Verify on Schematic :

Meissner 8-C FM Tuner 1949 Capacitor Inventory 06 I 16 K6VK

Electrolytic 3 orange 10 mfd @50 v 10 @450 25@25

Paper From top right .002 mfd @ 600v O.05@600 0.05@600 0.05@600 0.01@600 0.05@400 0.01@400 0.01@400

Ceramic 0.01 @?v Mica 0.005. Plus

Dot mica five; numbered now on schematic 4 Rectangle arrow longwise center; 3 are yellow

#1 One side arrow at front Top red dot red body Down arrow red green orange Other side red orange red Schematic says 0.0002@5% From 6c4 pin 5 to ground 6c4 towards front near var cap

#2 Yellow body Left of down arrow Blue gold red Blue purple blue 0.001@10% Across pins 2 & 6 1st 6ag5 Oo # 3 Yellow body Left of down arrow blue yellow red Right: blue brown blue Pin 5 1st 6ag5 to var cap Oo

#4 Yellow body Left of down arrow Blue yellow red Right of arrow Black yellow black 0.001@10% Goes to ground from coil Oo

#5 Red body high Left of arrow red orange brown Right: green yellow purple Schematic says 470mmf@10% From pin one 2d 6ag5 Oo

NB: the values of old Mica caps are very hard to read!

Locating And Getting Values For Mica Caps (and hoping they'll be good):



Mica caps are usually still good; at least many paper caps are usually bad.

Mica Caps, Color-coded, Read By Arrow:





So, what are the two bottom colors on this one?

What arrow?

And, what do the colors mean, where, in 1948? It's best to go by the schematic.

Replace All Electrolytic Capacitors but Beware Ambiguity!

This Plus Sign +, (in the temperature limits), wraps to the Negative side of the cap!

New Filter Electrolytics Bridged-in Over The Old Can:



Various insulations applied after replacement.

Re-capped:

But note the new three-wire linecord at the top; when the chassis was thus grounded, hum was introduced into a nearby radio. So, a polarized two-wire line cord was used.



A New Polarized Linecord Inserted, Hot To The Switch:



Some Resistance Is Futile: This Resistor Is Open And Unconnected On One Side:



This and other evidence suggests this tuner has been worked on before...

Success: The Tuner Works Just Fine! A nice warm sound...



But then I broke the 70-year-old dial-string by turning too hard at 108 MHz! So, I restrung it with braided fishing line. This worked well. (In the photo, the old string lies on the control.) The earlier photo of the original dialstringing came in handy!

When I broke the dial-string, my self-castigation, coded in obscenities, could likely be heard quite far from my bench!

Re-finishing The Cabinet:

I touched-up the black edging with black primer on a cotton swab, and then used wax. Kiwi shoe polish actually works best.



This cabinet appeared to have been refinished in the past, because some little edge chips had a finish over them but others did not. The present finish looks like polyurethane. The gunk on the chassis suggested prior residence in the home of a smoker. (confirmed perhaps by the residue on the polishing cloth). So I used **Restore-a-Shine**. which is mildly abrasive.

Save The Decal; Rub Off The Schmutz And Grime:



Cleaning The Outside Of The Dial With A Cotton Swab And Warm Water:



Trying to clean the inside, paint-side, of the dial puts the markings at risk!

The Working Meissner 8C Tuner In Its New Home: Great Sound!



A discone antenna on the roof provides the signals; a 1957 Masco amplifier sends the audio out to a big speaker and it sounds really good as a vacuum tube audio chain!

The Chicago FM Station List Taped To The Front; WLS Came On The Air With These Call-letters In 1964:

AND TRANSFORME	and the second second	THE REAL PROPERTY AND INCOME.
	FM STATIONS	
F WEELER CO.1	WDHF 95.5	WCLM 101.9
WANTH 88.5	WUSM JOL	WOUL 1027
WNUR 89.3	WNIB 97.1	WEEF 103.1
WMB1 90,1	WSDM 97.9	WKFM 103.5
WBEZ 91.5	WRSV 98.3	WJJD 104.3
WYCA \$2,3	WEMT 98.7	WEAW 105.1
WINVVC 92.7	WEFN 77.1	WAPA 105.9
WXRT 93.1	WPWF 100.3	WELF 107.7
WEBH 93.9	WMAQ 101.1	WNUS 107.5
WLS 94.7		All all the second second second
	The state of the second second second	and the state of the

Meissner was an Illinois company.

If Need Be, Diagnostics Are Available:









The Meissner 8C and a Thordardson Amp Sold Together In 1948; And Another Set is Still Together Today:

<<From Popular Mechanics, Feb. 1948, p. 229, a press-release article.

From E-Bay >>



Meissner Pre -WW II "Receptor" Covering the Old Armstrong FM Band of 40 – 52 MHz, Model 9-1053:



These pre-war FM radios are great to listen to today, in California, because the California Highway Patrol uses the band today and the wide-band reception of the broadcast circuitry permits all CHP stations to be heard at once.

Please Add More Information!

Corrections, suggestions and amplifications are welcome. Send to: <u>KV6LEE@gmail.com</u>.

This presentation is copyright Bart Lee, 2017 (who is a Fellow of the California Historical Radio Society) but any reasonable use may be made of it in furtherance of radio history and the history of this technology, respecting by proper attribution its authorship and integrity. All moral rights are asserted.

See www.californiahistoricalradio.com



73 de Bart, K6VK ##